

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	24/03/2025		M57 Pretoria Road - 1619
Inspection Date	24/03/2025		Kempton Park - GT

Vehicle Data


Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	LM95VGGP
Model	AMAROK 3.0 TDI D-CAB 4MOTION HIGHLINE DSL PU AT [2017-2019]	Register Number	
VIN	WV1ZZZ2HZJA001861	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	28/02/2025
Color	BLUE	Power / Displacement	
Year Model	2017	Paint Finish	M - METALLIC
Km Reading	149,778 KM	Fuel	DIESEL
Cab / Body Type	DOUBLE CAB	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Leak	Repair
Windscreen Wiper Malfunction	Repair
Differential Oil Leak	Repair
Electronics malfunction	Signs of spray work done on some body panels
Electronics malfunction	secure lid faulty
Engine	Bottom of engine is fully covered
wiper blades not working electrical malfunction	Repair



Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [KN]	Braking Force [KN]		
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/55R20	113V	Dunlop	Grandtrek	V	1723	3 mm
Front Right	265/55R20	113V	Dunlop	Grandtrek	V	1423	5 mm
Rear Left	265/55R20	113V	Dunlop	Grandtrek	V	1723	5 mm
Rear Right	265/55R20	113V	Dunlop	Grandtrek	V	1723	5 mm
Spare	255/50R20	109H	Bridgestone	Dueler	V	0000	5 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ELECTRONICS CENTRAL ELECTRIC	00975:011	REAR WINDOW DEFOGGER OPEN CIRCUIT	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks


THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician


Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



Shock test



Diagnostic test

N: WV1ZZZ2HZJA001861

2 / 7



Diagnostic test



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

VIN: WV1ZZZ2HZJA001861

3 / 7



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

VIN: WV1ZZZ2HZJA001861

5 / 7




90 DEGREE LEFT



LF TYRE TREAD



RF TYRE TREAD



RR TYRE TREAD



LR TYRE TREAD



Sparewheel

VIN: WV1ZZZ2HZJA001861

6 / 7



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Rear end



Oil cap and dipstick



Expansion bottle



Water level



Engine



Differential



Windscreen Wiper



CONDITION REPORT

Report No: 2016812441

DATE
24/03/2025

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za