



CONDITION REPORT



Report No:
2017305141
DATE
30/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	30/09/2026		M57 Pretoria Road - 1619
Inspection Date	30/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	HW87BSGP
Model	TIGUAN ALLSPACE 2.0 TSI 132KW COMFORTLINE 4MOTION DSG [2018-2020]	Register Number	
VIN	WVGZZZ5NZKM013621	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/10/2025
Color	WHITE	Power / Displacement	
Year Model	2019	Paint Finish	C - COMMON
Km Reading	163,668 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZ5NZKM013621



CONDITION REPORT



Report No:
2017305141
DATE
30/09/2026



Damage

Repair Way

Bonnet stay and shocks Defective	Replace
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Chipmarks	Repair
Door Front Left Paintwork • Chipmarks	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Engine Performance Slippy Hesitation	Repair
Brakes	No brake test done vehicle is 4wd
Engine management lights illuminated	Repair

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	245/45R19	102W	Anchee	Ac818	V	0524	1 mm
Front Right	245/45R19	102W	Anchee	Ac818	V	1124	3 mm
Rear Left	245/45R19	102W	Anchee	Ac818	V	1124	3 mm
Rear Right	245/45R19	102W	Anchee	Ac818	V	1124	3 mm
Spare	T145/85R18	103M	Ling long	Temporary	V	0000	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZ5NZKM013621



CONDITION REPORT



Report No:
2017305141
DATE
30/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ACTIVE STATIC	P227900	INTAKE AIR SYSTEM LEAKAGE	

Inspection Conditions

No Test Drive
Rain at time of inspection
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZ5NZKM013621



CONDITION REPORT



Report No:
2017305141
DATE
30/09/2026

Vehicle Information				Test Results			
Make/Model	Year	Engine	Transmission	Test Date	Test Time	Test Location	Test Result
Toyota Hilux	2017	2.8L Diesel	5-Speed Manual	30/09/2026	14:30	DEKRA	Pass
Test Name	Test Result	Test Date	Test Time	Test Location	Test Result	Test Date	Test Time
Shock Absorber Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Brake Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Steering Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Light Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Wash/Wax Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30

Shock report

Vehicle Information				Test Results			
Make/Model	Year	Engine	Transmission	Test Date	Test Time	Test Location	Test Result
Toyota Hilux	2017	2.8L Diesel	5-Speed Manual	30/09/2026	14:30	DEKRA	Pass
Test Name	Test Result	Test Date	Test Time	Test Location	Test Result	Test Date	Test Time
Shock Absorber Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Brake Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Steering Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Light Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Wash/Wax Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30

Diagnostic report

Vehicle Information				Test Results			
Make/Model	Year	Engine	Transmission	Test Date	Test Time	Test Location	Test Result
Toyota Hilux	2017	2.8L Diesel	5-Speed Manual	30/09/2026	14:30	DEKRA	Pass
Test Name	Test Result	Test Date	Test Time	Test Location	Test Result	Test Date	Test Time
Shock Absorber Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Brake Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Steering Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Light Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Wash/Wax Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30

Diagnostic report

Vehicle Information				Test Results			
Make/Model	Year	Engine	Transmission	Test Date	Test Time	Test Location	Test Result
Toyota Hilux	2017	2.8L Diesel	5-Speed Manual	30/09/2026	14:30	DEKRA	Pass
Test Name	Test Result	Test Date	Test Time	Test Location	Test Result	Test Date	Test Time
Shock Absorber Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Brake Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Steering Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Light Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Wash/Wax Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30

Diagnostic report

Vehicle Information				Test Results			
Make/Model	Year	Engine	Transmission	Test Date	Test Time	Test Location	Test Result
Toyota Hilux	2017	2.8L Diesel	5-Speed Manual	30/09/2026	14:30	DEKRA	Pass
Test Name	Test Result	Test Date	Test Time	Test Location	Test Result	Test Date	Test Time
Shock Absorber Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Brake Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Steering Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Light Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Wash/Wax Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30

Diagnostic report

Vehicle Information				Test Results			
Make/Model	Year	Engine	Transmission	Test Date	Test Time	Test Location	Test Result
Toyota Hilux	2017	2.8L Diesel	5-Speed Manual	30/09/2026	14:30	DEKRA	Pass
Test Name	Test Result	Test Date	Test Time	Test Location	Test Result	Test Date	Test Time
Shock Absorber Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Brake Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Steering Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Light Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30
Wash/Wax Test	Pass	30/09/2026	14:30	DEKRA	Pass	30/09/2026	14:30

Diagnostic report

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVZZZ5NZKM013621



CONDITION REPORT




Report No:

2017305141

DATE

30/09/2026



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVZZZ5NZKM013621



CONDITION REPORT



Report No:
2017305141
DATE
30/09/2026



Automatic



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVZZZ5NZKM013621



CONDITION REPORT



Report No:

2017305141

DATE

30/09/2026



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZ5NZKM013621



CONDITION REPORT



Report No:
2017305141
DATE
30/09/2026



ENGINE 1



ENGINE 2



CHASSIS



Oil cap and dipstick



Expansion bottle



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZ5NZKM013621



CONDITION REPORT



Report No:
2017305141
DATE
30/09/2026



Bonnet stay and shocks



Door Rear Right



Door Front Right



Front Fender Right



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZ5NZKM013621



CONDITION REPORT



Report No:

2017305141

DATE

30/09/2026



Bonnet



Front Fender Left



Door Front Left



Door Rear Left



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZ5NZKM013621